

State of California — The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code: 3D/3CD
 Other Listings _____
 Review Code _____ Reviewer _____ Date _____

*Resource Name or Address 530 F Street
 P1. Other Identifier: None
 *P2. Location: *a. County Yolo
 b. Address 530 F Street
 *c. City Davis Zip 95616
 d. UTM: N/A
 e. USGS Quad: Davis Quadrangle
 *f. Other Locational Data (APN #): 070-194-002

*P3a. Description:
 This charming Tudor Revival Cottage was constructed in 1925. It is an excellent example of its style type. The house is roughly U-shape in plan, with two cross wings projecting toward the street. The wings are of similar design, but differing size, a factor that enhances the rustic, vernacular quality of the building. The multiple cross gable roof is steeply pitched. The front facing gable ends are trimmed with faux half timbering in a diamond pattern. The wing on the north side is the larger of the two and has a gabled side dormer which is finished with shingles. Gable ends and eaves are dipped. Fenestration is mixed. The north gable wall window consists of three tall, fixed, multi-light panels which are trimmed at the top with an elliptical wooden frame in-filled with stucco. A horizontally emphasized window is found on the center wall, between the two wings. This is a fixed center panel with narrow, multi-light sidelights. The smaller south projecting wing has paired, double hung cottage windows. Other fenestration consists primarily of double cottage windows. A concrete porch fills the area between the projecting wings and extends along the front south wing wall. The porch is enclosed by a low brick wall which is capped with a header row. The house has both an exterior brick chimney, located on the north facade, and an internal brick chimney which pierces the front slope of the principal roof. The house is clad with stucco. It retains its integrity of materials, workmanship, setting, location, feeling and association and contributes to a district eligible for the California Register.

P5. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



*P3b. Resource Attributes: HP2
 *P4. Resources Present: Building
 Structure Object Site
 District Element of District
 P5b. Description of Photo:
 View east
 *P6. Date Constructed/Age:
 1925 78years dd documented
 Prehistoric Historic
 Both
 *P7. Owner and Address:
 Lynne Journey
 530 F Street
 Davis, CA 95616
 *P8. Recorded by:
 Carol Roland
 Roland-Nawi Associates
 4829 Crestwood Way
 Sacramento, CA 95822
 *P9. Date Recorded: 04/07-10/2003
 *P10. Type of Survey: Intensive
 Reconnaissance Other
 Describe: Determination of
 Local District Eligibility
 *P11. Report Citation: none
 *Attachments: NONE Map
 Sheet Continuation Sheet
 Building, Structure, and Object Record

Linear Resource Record Archaeological Record District Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List):

