

State of California — The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code: 3D/3CD
 Other Listings _____
 Review Code _____ Reviewer _____ Date _____

*Resource Name or Address 508/510 F Street
 P1. Other Identifier: None
 *P2. .Location: *a. County Yolo
 b. Address 508/510 F Street
 *c. City Davis Zip 95616
 d. UTM: N/A
 e. USGS Quad: Davis Quadrangle
 *f. Other Locational Data (APN #): 070-194-007

***P3a. Description:**

According to John Lofland (*Old North Davis*, Yolo County Historical Society, 1999), this double bungalow was originally a single family dwelling constructed in 1929 and converted in 1940. It is rectangular in plan with a moderately pitched front gable roof. Gable and eave overhangs are minimal with dipped ends. This uncharacteristic bungalow treatment may be the result of the later alteration. The gable end is trimmed with an arrow fascia, as is the gable end of the porch roof. A central, gable roofed projecting porch is centered on the façade, framing the side-by-side duplex entry doors. The porch roof is supported on braced 2X4s. The porch appears to be a replacement, possibly added in 1940. It is not possible to discern the configuration of the original porch or if it has been enclosed to create the flat façade that the building presents to the street. Fenestration consists of eight-over-eight double hung windows. The pairing of these windows lends a strong horizontal emphasis to the front façade. The window sash and glazing are original, but it is unclear if their position was changed to accommodate the conversion in occupancy. The conversion of the house and the accompanying alterations to the porch, entry doors, and possibly the front façade, fall within the period of significance. Therefore, the house retains the integrity of the 1940 building. It appears to be unaltered and it contributes to a district eligible for the California Register.

***P3b. Resource Attributes:** HP2

P5. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



***P4. Resources Present:** Building
 Structure Object Site
 District Element of District

P5b. Description of Photo:

View east

***P6. Date Constructed/Age:**
 1929 74 years old documented
 Prehistoric Historic
 Both

***P7. Owner and Address:**
 Patricia Loomis
 PO Box 482
 Davis, CA 95617

***P8. Recorded by:**
 Carol Roland
 Roland-Nawi Associates
 4829 Crestwood Way
 Sacramento, CA 95822

***P9. Date Recorded:** 04/07-10/2003

***P10. Type of Survey:** Intensive
 Reconnaissance Other
Describe: Determination of
 Local District Eligibility

***P11. Report Citation:** none

***Attachments:** NONE Map
 Sheet Continuation Sheet
 Building, Structure, and Object Record
 Linear Resource Record

Archaeological Record District Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List):

